

CONFIDENTIAL

25X1

25X1

25X1

25X1

25X1

25X1

25X1



PRESENTATION FORM FOR GRAPHIC MATERIAL		DATE 10 March 1956
(Submit <input type="checkbox"/> in triplicate with process sheet attached)		
DIST: ORIG-GRAPHICS; DUPL-CASE FILE; TRIPL-SOURCE FILE; QUAD-FO RECORD		<input type="checkbox"/> GIFT <input type="checkbox"/> LOAN
AREA USSR		
SUBJECT Cement Plants/miscellaneous <i>15 Photos - REC</i>		
NUMBER OF ITEMS AND CATEGORY (Still photographs, negatives, or slides)		
<input type="checkbox"/> CONFIDENTIAL <input type="checkbox"/> RESTRICTED <input type="checkbox"/> SECRET <input checked="" type="checkbox"/> UNCLASSIFIED		
Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No		
DESCRIPTION OF MATERIAL		
A. Seven Views of Cement Plant at Caspi <input type="checkbox"/> /near Tiflis. Exposed during November 1931. This plant was built by the firm, F. L. Smith, of Copenhagen, Denmark.		
1. Perspective view of crusher plant. 2. Close-up of Kiln and stack with railroad in foreground. 3. View of conveyor. 4. Ground view of storage towers under construction with rail line in foreground. 5. Close-up looking down on storage tower construction. Shows considerable structural detail. 6. Long range view of storage tower under construction. Oncart in foreground. 7. Group of Danish construction engineers. F. L. Smith is at right.		
B. Cement Plant near Bryansk - November 1931. - <i>33 15N 34 20E 27N</i>		
1. Close-up showing details of a structural failure which occurred during the construction of an addition to the cement plant. This view shows details of construction techniques. 2. Another view of the structural failure. 3. Ground pressure testing near Bryansk cement plant. Power shovel shown working in background.		
FOR HEADQUARTERS USE ONLY		
DATE FORWARDED TO HQ BY GMP 21 March 1956		RETURN DEADLINE (IF LOAN) 19 April 1956
NITRATE FILM EXPLOSIVE-SHIP BY EXPRESS-UNDER SPECIAL CARRIER REGULATIONS		
FORM NO. 121 REPLACES FORM 57-27 FEB. 53 WHICH MAY BE USED.		

CONFIDENTIAL

CONFIDENTIAL

-2-

4. Another ground pressure testing site at Bryansk cement plant.
Building in background is part of plant.
5. Women repairing rail line near Bryansk.

25X1 C. Site of Proposed "Gigant" cement plant. 
 The construction of the plant was abandoned in 1931 but may have been built later.

25X1

1. View of workers cutting and stripping lumber for future construction.
2. Another shot of workers.

D. View of Grain loading at the elevator at Semipalatinsk. Freight cars shown in background.

25X1 

CONFIDENTIAL